

MONTHLY CCTV SERVICEABILITY REPORT:

MAY. 22

SUBMITTED ON

BY ARNAV ENTERPRISES

BLOCK NO	DVR NO	LOCATION	CAM NO	CLEANED	STATUS		REMARK / FAULT
					WORKING	NOT WORKING	
VP	DVR 3 (04)	RECEPTION	2		✓		
		PASSAGE BET W & VP	3		✓		
		OFFICE GRD FLR	4		✓		
		2 ND FLOOR CORRIDOR	7		✓		
VIT	DVR 1 (12)	BASEMENT CORRIDOR 1	8		✓		
		BASEMENT LIFT	9		✓		
		BASEMENT CORRIDOR 2	10		✓		
		VIT RECEPTION	13		✓		
		VIT ENTRY 1	14			X	Cable Faulty
		VIT PLAZA1 WALL	15		✓		
		VIT COMPUTER CENTRE	16		✓		
		VIT PLAZA 2	17			X	Cable Faulty
		DIRECTOR'S OFFICE	20		✓		
		PAPER PRINTING	143		✓		
		VP LAB 2	175		✓		
VSIT	DVR2 (12)	VIT ACCOUNT A BLK	176		✓		
		'X' BLOCK ENTRY	23		✓		
		'X' OFFICE -2	24				
		'X' GRD FLR CORRIDOR 1	25				
		'X' GRD FLR CORRIDOR 2	26				DVR Faulty
		'X' OFFICE	27				
		GROUND 1	31				
		PARKING STUDENTS	32				
		LIBRARY VSIT	144				
		TREE AREA X BLK	178				
		X 19 REASERCH CENTRE	179				
X 016 VSIT OFFICE	180						
X11 VSIT STAFF ROOM	181						
D	DVR4 (15)	BASEMENT CORRIDOR 3	11		✓		
		BASEMENT GYM	12		✓		
		VIT CANTEEN	18		✓		
		VIT ENTRY 2	19		✓		
		D-101 FACULTY	33		✓		
		D-102 CLASS	34		✓		
		D-103 OFFICE/DVR	35		✓		
		D-105 CLASS	36		✓		
		D-201 CLASS	37		✓		
		D-202 CLASS	38			X	Camera Faulty
		D-204 CLASS	39		✓		
		D-301 CLASS	40		✓		
		D-302 CLASS	41		✓		
D-304 CLASS	42		✓				
E	DVR 5	CANTEEN C BLK	190		✓		
		GROUND 2	21		✓		

	(14)	REAR GATE	22				
		E-101 CLASS	43				
		E-102 OFFICE/DVR	44				
		E-104 STATIONARY	45				
		M BLK CANTEEN	191				
		E-105 FACULTY	46				
		E-105 FACULTY	47				
		E-201 CLASS	48				
		E-204 CLASS	49				
		E-301 CLASS	50				
		E-303 CLASS	51				
		WORKSHOP M BLOCK	52				
		CANTEEN M BLOCK	142				
G	DVR 21 (8)	VIT CC02	182				
		VIT CC 03	183				
		G 201 REFERENCE	184				
		G BLK 1 ST FLR ENTRY	185				
		READING HALL	186				
		LIBRARY VIT 201	187				
		G 301 LIB	188				
		STORE F	189				
X1	DVR7 (16)	X-101 CLASS	53				
		X-102 CLASS	54				
		X-103 A LAB	55				
		X-103 B LAB	56				
		X-107 CLASS	57				
		X-108 CLASS	58				
		X-109 FACULTY ROOM	59				
		X-110 CLASS	60				
		X-111 CLASS	61				
		X-112 CLASS	62				
		X-113 CLASS	63				
		X-114 LAB	64				
		X-115 LAB	65				
		X-116 LAB	66				
		X-117 CLASS	67				
		X-118 CLASS	68				
X	DVR6 (08)	X-015 EXAM CELL	28				
		'X' 1 ST FLR CORRIDOR	29				
		'X' 1 ST FLR DEAD END	30				
		X-119 LAB	69				
		X-120 LAB	70				
		X-121 LAB	71				
		X-122 LAB	72				
		X-123 LAB	73				
VP LAB	DVR8 (16)	V 118 COM LAB	74				
		V119 COM LAB	75				
		V120 COM LAB	76				
		V 05 /5A PHYSICS LAB	77				
		V 06 CHEMISTRY LAB	165				
		V 07 PCB LAB	166				
		V REAR ENTRY 1 ST FLR	167				
		V STAIRCASE 1 ST FLR	168				
		V VISITORS AREA 1 ST FLR	5				
		V REAR CORIDOR 1 ST FLR	169				
		V OPEN CUBICALS REAR	6				

* Camera Faulty

		V OUTSIDE SEMINAR HALL	170		✓		
		V REAR CORIDOR 1 ST FLR	171			X	Camera Faulty
		V 105 SEMINAR HALL	172		✓		
		V REAR STAIRES	173		✓		
		V REAR ENTRY GRD FLR	174		✓		
VIT L 3	DVR9 (08)	LAB 1	78		✓		
		LIBRARY VP	79		✓		
		LAB 3	80		✓		
		LAB 4	81		✓		
		LAB 5	82		✓		
		LAB 6	83		✓		
		LAB 7	84		✓		
		LAB 17	85		✓		
VIT LAB	DVR 10 (8)	LAB 9	86		✓		
		LAB 10	87			X	Camera Faulty
		LAB 11	88		✓		
		LAB 12	89		✓		
		LAB 13	90		✓		
		LAB 14	91			X	Camera Faulty
		LAB 15	92		✓		
		LAB 16	93		✓		
M 1	DVR11 (C5)	RECEPTION	94		✓		
		OUTSIDE LIFT 3 & 4	95		✓		
		STAIRCASE FRONT	96		✓		
		OUTSIDE LIFT 1 & 2	97		✓		
		STAIRCASE REAR	98		✓		
M 2	DVR12 (C4)	STAIRCASE REAR	99				DVR Power Supply Faulty
		OUTSIDE LIFT 1 & 2	100				
		STAIRCASE FRONT	101				
		LAB 201	102				
M 3	DVR13 (08)	LOBBY	103		✓		
		LAB 312	104		✓		
		LAB 310	105		✓		
		STAIRCASE FRONT	106		✓		
		OUTSIDE LIFT 1 & 2	107		✓		
		LAB 313	108		✓		
		STAIRCASE REAR	109		✓		
		LAB 314	110		✓		
M 4	DVR14 (08)	LOBBY	111		✓		
		LAB 414	112		✓		
		LAB 411	113		✓		
		STAIRCASE FRONT	114		✓		
		LAB 401	115		✓		
		TOWARDS VIT TERRACE	116		✓		
		STAIRCASE REAR	117		✓		
		OUTSIDE LIFT 1 & 2	118		✓		
M 5	DVR15 (10)	STAIRCASE FRONT	119		✓		
		STAIRCASE REAR	120		✓		
		LAB 516	121		✓		
		LAB 512	122		✓		
		LAB 510	123		✓		
		LAB 509	124		✓		
		LAB 514	125		✓		
		LAB 518	126		✓		
		OUTSIDE LIFT 1 & 2	127		✓		

M 6	DVR16 (04)	LAB 515	128	✓		
		STAIRCASE FRONT	129	✓		
		LOBBY	130	✓		
		STAIRCASE REAR	131	✓		
M 7	DVR17 (09)	OFFICE MMS	132	✓		
		OFFICE CORRIDOR	133	✓		
		STAIRCASE REAR	134	✓		
		STAIRCASE FRONT	135	✓		
		RECEPTION LOBBY	136	✓		
		PANTRY	137	✓		
		LIFT 1	138			X Camera Fully
		LIFT 2	139			X camera fully
RG	DVR 18 (03)	LIFT 3	140	✓		
		LIFT 4	141	✓		
		REAR GATE ENTRY	145	✓		
S	DVR 19 (16)	STP AREA	146	✓		OFF line
		ROAD FROM RG	147			
		OUT SIDE ENTRY POINT	148	✓		
Y	DVR 20 (10)	RECEPTION	149	✓		
		KARAOKE ROOM	150	✓		
		TT ROOM	151	✓		
		MERCHANTILE ROOM	152	✓		
		CHESS ROOM	153	✓		
		GAME ZONE	154	✓		
		MEETING ROOM	155	✓		
		BAG RACK	194	✓		
		OPP.CCD FLOOR	156	✓		
		OPP.CCD FLOOR	157	✓		
M GATE	DVR 21	OUTSIDE SICK ROOM	158	✓		
		GLASS DOOR ENTRY	159	✓		
		READING ROOM	160	✓		
		READING ROOM	161	✓		
		LAB	162	✓		
M GATE	DVR 21	LAB CORIDOR	163	✓		
		1 ST FLR ENTRY TO X BLOK	164	✓		
		Y BLK STAFF ROOM	177	✓		
M GATE	DVR 21	4 C AREA	195	✓		
		MAIN GATE CAMPUS	1	✓		
		2 ND GATE	192	✓		
M GATE	DVR 21	PARKING	193	✓		

TOTAL 195CAMS							
DVR SERVICEABILITY STATUS							
DVR	LOCATION	SERVICEABLE	NETCO NNECT	RECORD ING	HDD	REMARK	
VP	V- PLACEMENT	215		62	1 TB		
VIT	RECEPTION			36	1 TB		
VSIT	OFFICE					2 TB	
VIT D BLOCK	D-103				32	2 TB	
VIT E BLOCK	E-102				27	2 TB	

X1	OFFICE	✓		36	2 TB
X	OFFICE	✓		22	1 TB
VP LAB	V-123	✓		58	4 TB
B 1	L-014	✓		35	1 TB
B 2	L-003	✓		38	1 TB
M-1	REAR DUCT	✓		63	2 TB
M-2	REAR DUCT	✓		22	1 TB
M-3	REAR DUCT	✓		52	2 TB
M-4	REAR DUCT	✓		42	2 TB
M-5	REAR DUCT	✓			2 TB
M-6	REAR DUCT	✓		31	1 TB
M-7	LOBBY ROOF	✓		28	2 TB
RG	RG	✓		23	1 TB
Y	OUT SIDE READING ROOM	✓		18	1 TB
S	GR.FLR. RECPT.	✓		33	2 TB
G	NR.STAIRE CASE	✓		28	2 TB
M GATE	SEC OFF	✓		45	1 TB

CCTV REPORT IN NUTSHELL

TIME TAKEN FOR MAINTENANCE	02:30
SPECIFIC WORK DONE	checking the camera
WORK REQUIRED TO BE DONE	check the camera for 2 hours
NO OF WORKERS REPORTED FOR MAINTENANCE	2
CLIENT REMARKS	ok

00/00/00
ARNAV ENTERPRISES

SEC SUP

SEC OFFICER

MONTHLY CCTV SERVICEABILITY REPORT:

APR-02

SUBMITTED ON

5/22

BY ARNAV ENTERPRISES

BLOCK NO	DVR NO	LOCATION	CAM NO	CLEANED	STATUS		REMARK / FAULT
					WORKING	NOT WORKING	
VP	DVR 3 (04)	RECEPTION	2				
		PASSAGE BET W & VP	3				
		OFFICE GRD FLR	4				
		2 ND FLOOR CORRIDOR	7				
VIT	DVR 1 (12)	BASEMENT CORRIDOR 1	8				
		BASEMENT LIFT	9				
		BASEMENT CORRIDOR 2	10				
		VIT RECEPTION	13				
		VIT ENTRY 1	14				
		VIT PLAZA1 WALL	15				
		VIT COMPUTER CENTRE	16				
		VIT PLAZA 2	17				
		DIRECTOR'S OFFICE	20				
		PAPER PRINTING	143				
		VP LAB 2	175				
		VIT ACCOUNT A BLK	176				
VSIT	DVR2 (12)	'X' BLOCK ENTRY	23				
		'X' OFFICE -2	24				
		'X' GRD FLR CORRIDOR 1	25				
		'X' GRD FLR CORRIDOR 2	26				
		'X' OFFICE	27				
		GROUND 1	31				
		PARKING STUDENTS	32				
		LIBRARY VSIT	144				
		TREE AREA X BLK	178				
		X 19 REASERCH CENTRE	179				
		X 016 VSIT OFFICE	180				
		X11 VSIT STAFF ROOM	181				
D	DVR4 (15)	BASEMENT CORRIDOR 3	11				
		BASEMENT GYM	12				
		VIT CANTEEN	18				
		VIT ENTRY 2	19				
		D-101 FACULTY	33				
		D-102 CLASS	34				
		D-103 OFFICE/DVR	35				
		D-105 CLASS	36				
		D-201 CLASS	37				
		D-202 CLASS	38				
		D-204 CLASS	39				
		D-301 CLASS	40				
		D-302 CLASS	41				
D-304 CLASS	42						
CANTEEN C BLK	190						
E	DVR 5	GROUND 2	21				

	(14)	REAR GATE	22			
		E-101 CLASS	43			
		E-102 OFFICE/DVR	44			
		E-104 STATIONARY	45			
		M BLK CANTEEN	191			
		E-105 FACULTY	46			
		E-105 FACULTY	47			
		E-201 CLASS	48			
		E-204 CLASS	49			
		E-301 CLASS	50			
		E-303 CLASS	51			
		WORKSHOP M BLOCK	52			
		CANTEEN M BLOCK	142			
G	DVR 21 (8)	VIT CC02	182			
		VIT CC 03	183			
		G 201 REFERENCE	184			
		G BLK 1 ST FLR ENTRY	185			
		READING HALL	186			
		LIBRARY VIT 201	187			
		G 301 LIB	188			
		STORE F	189			
X1	DVR7 (16)	X-101 CLASS	53			
		X-102 CLASS	54			
		X-103 A LAB	55			
		X-103 B LAB	56			
		X-107 CLASS	57			
		X-108 CLASS	58			
		X-109 FACULTY ROOM	59			
		X-110 CLASS	60			
		X-111 CLASS	61			
		X-112 CLASS	62			
		X-113 CLASS	63			
		X-114 LAB	64			
		X-115 LAB	65			
		X-116 LAB	66			
		X-117 CLASS	67			
		X-118 CLASS	68			
X	DVR6 (08)	X-015 EXAM CELL	28			
		'X' 1 ST FLR CORRIDOR	29			
		'X' 1 ST FLR DEAD END	30			
		X-119 LAB	69			
		X-120 LAB	70			
		X-121 LAB	71			
		X-122 LAB	72			
		X-123 LAB	73			
VP LAB	DVR8 (16)	V 118 COM LAB	74			
		V119 COM LAB	75			
		V120 COM LAB	76			
		V 05 /5A PHYSICS LAB	77			
		V 06 CHEMISTRY LAB	165			
		V 07 PCB LAB	166			
		V REAR ENTRY 1 ST FLR	167			
		V STAIRCASE 1 ST FLR	168			
		V VISITORS AREA 1 ST FLR	5			
		V REAR CORRIDOR 1 ST FLR	169			
		V OPEN CUBICALS REAR	6			

Camera Entry

Camera Entry

		V OUTSIDE SEMINAR HALL	170	✓		
		V REAR CORIDOR 1 ST FLR	171		✗	Room empty
		V 105 SEMINAR HALL	172	✓		
		V REAR STAIRES	173	✓		
		V REAR ENTRY GRD FLR	174	✓		
VIT L 3	DVR9 (08)	LAB 1	78	✓		
		LIBRARY VP	79	✓		
		LAB 3	80	✓		
		LAB 4	81	✓		
		LAB 5	82	✓		
		LAB 6	83	✓		
		LAB 7	84	✓		
		LAB 17	85	✓		
VIT LAB	DVR 10 (8)	LAB 9	86	✓		
		LAB 10	87		✗	Camera faulty
		LAB 11	88	✓		
		LAB 12	89	✓		
		LAB 13	90	✓		
		LAB 14	91		✗	Camera faulty
		LAB 15	92			
		LAB 16	93	✓		
M 1	DVR11 (05)	RECEPTION	94	✓		
		OUTSIDE LIFT 3 & 4	95	✓		
		STAIRCASE FRONT	96	✓		
		OUTSIDE LIFT 1 & 2	97	✓		
		STAIRCASE REAR	98	✓		
M 2	DVR12 (04)	STAIRCASE REAR	99			} DVR Power Supply Faulty
		OUTSIDE LIFT 1 & 2	100			
		STAIRCASE FRONT	101			
		LAB 201	102			
M 3	DVR13 (08)	LOBBY	103	✓		
		LAB 312	104	✓		
		LAB 310	105	✓		
		STAIRCASE FRONT	106	✓		
		OUTSIDE LIFT 1 & 2	107	✓		
		LAB 313	108	✓		
		STAIRCASE REAR	109	✓		
		LAB 314	110	✓		
M 4	DVR14 (08)	LOBBY	111	✓		
		LAB 414	112	✓		
		LAB 411	113	✓		
		STAIRCASE FRONT	114	✓		
		LAB 401	115	✓		
		TOWARDS VIT TERRACE	116	✓		
		STAIRCASE REAR	117	✓		
		OUTSIDE LIFT 1 & 2	118	✓		
M 5	DVR15 (10)	STAIRCASE FRONT	119	✓		
		STAIRCASE REAR	120	✓		
		LAB 516	121	✓		
		LAB 512	122	✓		
		LAB 510	123	✓		
		LAB 509	124	✓		
		LAB 514	125	✓		
		LAB 518	126	✓		
		OUTSIDE LIFT 1 & 2	127	✓		

M 6	DVR16 (04)	LAB 515	128				
		STAIRCASE FRONT	129				
		LOBBY	130				
		STAIRCASE REAR	131				
M 7	DVR17 (09)	OFFICE MMS	132				
		OFFICE CORRIDOR	133				
		STAIRCASE REAR	134				
		STAIRCASE FRONT	135				
		RECEPTION LOBBY	136				
		PANTRY	137				
		LIFT 1	138			X	Camera Fault
		LIFT 2	139			X	Camera Fault
		LIFT 3	140				
		LIFT 4	141				
RG	DVR 18 (03)	REAR GATE ENTRY	145				
		STP AREA	146				OFF line
		ROAD FROM RG	147				
S	DVR 19 (16)	OUT SIDE ENTRY POINT	148				
		RECEPTION	149				
		KARAOKE ROOM	150				
		TT ROOM	151				
		MERCHANTILE ROOM	152				
		CHESS ROOM	153				
		GAME ZONE	154				
		MEETING ROOM	155				
Y	DVR 20 (10)	BAG RACK	194				
		OPP.CCD FLOOR	156				
		OPP.CCD FLOOR	157				
		OUTSIDE SICK ROOM	158				
		GLASS DOOR ENTRY	159				
		READING ROOM	160				
		READING ROOM	161				
		LAB	162				
		LAB CORIDOR	163				
		1 ST FLR ENTRY TO X BLOK	164				
		Y BLK STAFF ROOM	177				
		4 C AREA	195				
M GATE	DVR 21	MAIN GATE CAMPUS	1				
		2 ND GATE	192				
		PARKING	193				

TOTAL 195CAMS						
DVR SERVICEABILITY STATUS						
DVR	LOCATION	SERVICEABLE	NETCO NNECT	RECORD ING	HDD	REMARK
VP	V- PLACEMENT	✓		62	1 TB	
VIT	RECEPTION	✓		36	1 TB	
VSIT	OFFICE	✓			2 TB	
VIT D BLOCK	D-103	✓		32	2 TB	
VIT E BLOCK	E-102	✓		27	2 TB	

X1	OFFICE		36	2 TB
X	OFFICE		22	1 TB
VP LAB	V-123		58	4 TB
B 1	L-014		35	1 TB
B 2	L-003		38	1 TB
M- 1	REAR DUCT		68	2 TB
M- 2	REAR DUCT		22	1 TB
M- 3	REAR DUCT		52	2 TB
M- 4	REAR DUCT		42	2 TB
M- 5	REAR DUCT			2 TB
M- 6	REAR DUCT		37	1 TB
M- 7	LOBBY ROOF		28	2 TB
RG	RG		23	1 TB
Y	OUT SIDE READING ROOM		18	1 TB
S	GR.FLR. RECPT.		33	2 TB
G	NR.STAIRE CASE		28	2 TB
M GATE	SEC OFF		45	1 TB

CCTV REPORT IN NUTSHELL

TIME TAKEN FOR MAINTENANCE	
SPECIFIC WORK DONE	
WORK REQUIRED TO BE DONE	
NO OF WORKERS REPORTED FOR MAINTENANCE	
CLIENT REMARKS	

() ()
 ARNAV ENTERPRISES *Mishra* SEC SUP *Mishra* SEC OFFICER

MONTHLY CCTV SERVICEABILITY REPORT:

Mar 22

SUBMITTED ON

7/3/2022

BY ARNAV ENTERPRISES

BLOCK NO	DVR NO	LOCATION	CAM NO	CLEANED	STATUS		REMARK / FAULT	
					WORKING	NOT WORKING		
VP	DVR 3 (04)	RECEPTION	2		✓			
		PASSAGE BET W & VP	3		✓			
		OFFICE GRD FLR	4		✓			
		2 ND FLOOR CORRIDOR	7		✓			
VIT	DVR 1 (12)	BASEMENT CORRIDOR 1	8			X	Camera in Blk 2	
		BASEMENT LIFT	9		✓			
		BASEMENT CORRIDOR 2	10		✓			
		VIT RECEPTION	13		✓			
		VIT ENTRY 1	14				X	Camera in Blk 2
		VIT PLAZA1 WALL	15		✓			
		VIT COMPUTER CENTRE	16		✓			
		VIT PLAZA 2	17				X	Camera in Blk 2
		DIRECTOR'S OFFICE	20		✓			
		PAPER PRINTING	143		✓			
		VP LAB 2	175		✓			
		VIT ACCOUNT A BLK	176		✓			
		VSIT	DVR 2 (12)	'X' BLOCK ENTRY	23			
'X' OFFICE -2	24							
'X' GRD FLR CORRIDOR 1	25							
'X' GRD FLR CORRIDOR 2	26						X	Camera in Blk 2
'X' OFFICE	27							
GROUND 1	31							
PARKING STUDENTS	32							
LIBRARY VSIT	144							
TREE AREA X BLK	178							
X 19 REASERCH CENTRE	179							
X 016 VSIT OFFICE	180							
X11 VSIT STAFF ROOM	181							
D	DVR 4 (15)	BASEMENT CORRIDOR 3	11		✓			
		BASEMENT GYM	12		✓			
		VIT CANTEEN	18		✓			
		VIT ENTRY 2	19		✓			
		D-101 FACULTY	33		✓			
		D-102 CLASS	34		✓			
		D-103 OFFICE/DVR	35		✓			
		D-105 CLASS	36		✓			
		D-201 CLASS	37		✓			
		D-202 CLASS	38				X	Camera in Blk 2
		D-204 CLASS	39		✓			
		D-301 CLASS	40		✓			
		D-302 CLASS	41		✓			
		D-304 CLASS	42		✓			
CANTEEN C BLK	190		✓					
E	DVR 5	GROUND 2	21		✓			

	(14)	REAR GATE	22				
		E-101 CLASS	43				
		E-102 OFFICE/DVR	44				
		E-104 STATIONARY	45				
		M BLK CANTEEN	191				
		E-105 FACULTY	46				
		E-105 FACULTY	47				
		E-201 CLASS	48				
		E-204 CLASS	49				
		E-301 CLASS	50				
		E-303 CLASS	51				
		WORKSHOP M BLOCK	52				
		CANTEEN M BLOCK	142				
G	DVR 21 (8)	VIT CC02	182				
		VIT CC 03	183				
		G 201 REFERENCE	184				
		G BLK 1 ST FLR ENTRY	185				
		READING HALL	186				
		LIBRARY VIT 201	187				
		G 301 LIB	188				
		STORE F	189				
X1	DVR7 (16)	X-101 CLASS	53				
		X-102 CLASS	54				
		X-103 A LAB	55				
		X-103 B LAB	56				
		X-107 CLASS	57				
		X-108 CLASS	58				
		X-109 FACULTY ROOM	59				
		X-110 CLASS	60				
		X-111 CLASS	61				
		X-112 CLASS	62				
		X-113 CLASS	63				
		X-114 LAB	64				
		X-115 LAB	65				
		X-116 LAB	66				
		X-117 CLASS	67				
		X-118 CLASS	68				
X	DVR6 (08)	X-015 EXAM CELL	28				
		'X' 1 ST FLR CORRIDOR	29				
		'X' 1 ST FLR DEAD END	30				
		X-119 LAB	69				
		X-120 LAB	70				
		X-121 LAB	71				
		X-122 LAB	72				
		X-123 LAB	73				
VP LAB	DVR8 (16)	V 118 COM LAB	74				
		V119 COM LAB	75				
		V120 COM LAB	76				
		V 05 /5A PHYSICS LAB	77				
		V 06 CHEMISTRY LAB	165				
		V 07 PCB LAB	166				
		V REAR ENTRY 1 ST FLR	167				
		V STAIRCASE 1 ST FLR	168				
		V VISITORS AREA 1 ST FLR	5				
		V REAR CORIDOR 1 ST FLR	169				
		V OPEN CUBICALS REAR	6				

		V OUTSIDE SEMINAR HALL	170				
		V REAR CORIDOR 1 ST FLR	171				
		V 105 SEMINAR HALL	172				
		V REAR STAIRES	173				
		V REAR ENTRY GRD FLR	174				
VIT L 3	DVR9 (08)	LAB 1	78				
		LIBRARY VP	79				
		LAB 3	80				
		LAB 4	81				
		LAB 5	82				
		LAB 6	83				
		LAB 7	84				
		LAB 17	85				
VIT LAB	DVR 10 (8)	LAB 9	86				
		LAB 10	87				
		LAB 11	88				
		LAB 12	89				
		LAB 13	90				
		LAB 14	91				
		LAB 15	92				
		LAB 16	93				
M 1	DVR11 (05)	RECEPTION	94				
		OUTSIDE LIFT 3 & 4	95				
		STAIRCASE FRONT	96				
		OUTSIDE LIFT 1 & 2	97				
		STAIRCASE REAR	98				
M 2	DVR12 (04)	STAIRCASE REAR	99				
		OUTSIDE LIFT 1 & 2	100				
		STAIRCASE FRONT	101				
		LAB 201	102				
M 3	DVR13 (08)	LOBBY	103				
		LAB 312	104				
		LAB 310	105				
		STAIRCASE FRONT	106				
		OUTSIDE LIFT 1 & 2	107				
		LAB 313	108				
		STAIRCASE REAR	109				
		LAB 314	110				
M 4	DVR14 (08)	LOBBY	111				
		LAB 414	112				
		LAB 411	113				
		STAIRCASE FRONT	114				
		LAB 401	115				
		TOWARDS VIT TERRACE	116				
		STAIRCASE REAR	117				
		OUTSIDE LIFT 1 & 2	118				
M 5	DVR15 (10)	STAIRCASE FRONT	119				
		STAIRCASE REAR	120				
		LAB 516	121				
		LAB 512	122				
		LAB 510	123				
		LAB 509	124				
		LAB 514	125				
		LAB 518	126				
		OUTSIDE LIFT 1 & 2	127				

M 6	DVR 16 (04)	LAB 515	128			
		STAIRCASE FRONT	129			
		LOBBY	130			
		STAIRCASE REAR	131			
M 7	DVR 17 (09)	OFFICE MMS	132			
		OFFICE CORRIDOR	133			
		STAIRCASE REAR	134			
		STAIRCASE FRONT	135			
		RECEPTION LOBBY	136			
		PANTRY	137			
		LIFT 1	138			
		LIFT 2	139			
RG	DVR 18 (03)	REAR GATE ENTRY	145			
		STP AREA	146			
		ROAD FROM RG	147			
S	DVR 19 (16)	OUT SIDE ENTRY POINT	148			
		RECEPTION	149			
		KARAOKE ROOM	150			
		TT ROOM	151			
		MERCHANTILE ROOM	152			
		CHESS ROOM	153			
		GAME ZONE	154			
		MEETING ROOM	155			
Y	DVR 20 (10)	BAG RACK	194			
		OPP.CCD FLOOR	156			
		OPP.CCD FLOOR	157			
		OUTSIDE SICK ROOM	158			
		GLASS DOOR ENTRY	159			
		READING ROOM	160			
		READING ROOM	161			
		LAB	162			
		LAB CORIDOR	163			
		1 ST FLR ENTRY TO X BLOK	164			
		Y BLK STAFF ROOM	177			
M GATE	DVR 21	4 C AREA	195			
		MAIN GATE CAMPUS	1			
		2 ND GATE	192			
		PARKING	193			

TOTAL 195CAMS

DVR SERVICEABILITY STATUS

DVR	LOCATION	SERVICEABLE	NETCO NNECT	RECORD ING	HDD	REMARK
VP	V- PLACEMENT				1 TB	
VIT	RECEPTION				1 TB	
VSIT	OFFICE				2 TB	
VIT D BLOCK	D-103				2 TB	
VIT E BLOCK	E-102				2 TB	

X1	OFFICE				2 TB	
X	OFFICE				1 TB	
VP LAB	V-123				4 TB	
B 1	L-014				1 TB	
B 2	L-003				1 TB	
M- 1	REAR DUCT				2 TB	
M- 2	REAR DUCT				1 TB	
M- 3	REAR DUCT				2 TB	
M- 4	REAR DUCT				2 TB	
M- 5	REAR DUCT				2 TB	
M- 6	REAR DUCT				1 TB	
M-7	LOBBY ROOF				2 TB	
RG	RG				1 TB	
Y	OUT SIDE READING ROOM				1 TB	
S	GR.FLR. RECPT.				2 TB	
G	NR.STAIRE CASE				2 TB	
M GATE	SEC OFF				1 TB	

CCTV REPORT IN NUTSHELL

TIME TAKEN FOR MAINTENANCE	
SPECIFIC WORK DONE	
WORK REQUIRED TO BE DONE	
NO OF WORKERS REPORTED FOR MAINTENANCE	
CLIENT REMARKS	

() ()
ARNAV ENTERPRISES

SEC SUP

SEC OFFICER

MONTHLY CCTV SERVICEABILITY REPORT:

Feb-22

SUBMITTED ON

15-03-22

BY ARNAV ENTERPRISES

BLOCK NO	DVR NO	LOCATION	CAM NO	CLEANED	STATUS		REMARK / FAULT
					WORKING	NOT WORKING	
VP	DVR 3 (04)	RECEPTION	2		✓		
		PASSAGE BET W & VP	3		✓		
		OFFICE GRD FLR	4		✓		
		2 ND FLOOR CORRIDOR	7		✓		
VIT	DVR 1 (12)	BASEMENT CORRIDOR 1	8				X camera faulty
		BASEMENT LIFT	9		✓		
		BASEMENT CORRIDOR 2	10		✓		
		VIT RECEPTION	13		✓		
		VIT ENTRY 1	14				X cable faulty
		VIT PLAZA1 WALL	15		✓		
		VIT COMPUTER CENTRE	16		✓		
		VIT PLAZA 2	17				X cable and camera faulty
		DIRECTOR'S OFFICE	20		✓		
		PAPER PRINTING	143		✓		
		VP LAB 2	175		✓		
		VIT ACCOUNT A BLK	176		✓		
		VSIT	DVR2 (12)	'X' BLOCK ENTRY	23		
'X' OFFICE -2	24						
'X' GRD FLR CORRIDOR 1	25						
'X' GRD FLR CORRIDOR 2	26						
'X' OFFICE	27						
GROUND 1	31						
PARKING STUDENTS	32						
LIBRARY VSIT	144						
TREE AREA X BLK	178						
X 19 REASERCH CENTRE	179						
X 016 VSIT OFFICE	180						
X11 VSIT STAFF ROOM	181						
D	DVR4 (15)			BASEMENT CORRIDOR 3	11		✓
		BASEMENT GYM	12		✓		
		VIT CANTEEN	18		✓		
		VIT ENTRY 2	19		✓		
		D-101 FACULTY	33		✓		
		D-102 CLASS	34		✓		
		D-103 OFFICE/DVR	35		✓		
		D-105 CLASS	36		✓		
		D-201 CLASS	37		✓		
		D-202 CLASS	38				X camera faulty
		D-204 CLASS	39		✓		
		D-301 CLASS	40		✓		
		D-302 CLASS	41		✓		
		D-304 CLASS	42		✓		
CANTEEN C. BLK	190		✓				
E	DVR 5	GROUND 2	21				

	(14)	REAR GATE	22				
		E-101 CLASS	43				
		E-102 OFFICE/DVR	44				
		E-104 STATIONARY	45				
		M BLK CANTEEN	191				
		E-105 FACULTY	46				
		E-105 FACULTY	47				
		E-201 CLASS	48				
		E-204 CLASS	49				
		E-301 CLASS	50				
		E-303 CLASS	51				
		WORKSHOP M BLOCK	52				
		CANTEEN M BLOCK	142				
G	DVR 21 (8)	VIT CC02	182				
		VIT CC 03	183				
		G 201 REFERENCE	184				
		G BLK 1 ST FLR ENTRY	185				
		READING HALL	186				
		LIBRARY VIT 201	187				
		G 301 LIB	188				
		STORE F	189				
X1	DVR7 (16)	X-101 CLASS	53				
		X-102 CLASS	54				
		X-103 A LAB	55				
		X-103 B LAB	56				
		X-107 CLASS	57				
		X-108 CLASS	58				
		X-109 FACULTY ROOM	59				
		X-110 CLASS	60			x	cameraed fully
		X-111 CLASS	61				
		X-112 CLASS	62				
		X-113 CLASS	63				
		X-114 LAB	64				
		X-115 LAB	65				
		X-116 LAB	66				
		X-117 CLASS	67				
		X-118 CLASS	68				
X	DVR6 (08)	X-015 EXAM CELL	28				
		'X' 1 ST FLR CORRIDOR	29				
		'X' 1 ST FLR DEAD END	30				
		X-119 LAB	69			x	cameraed fully
		X-120 LAB	70				
		X-121 LAB	71				
		X-122 LAB	72				
		X-123 LAB	73				
VP LAB	DVR8 (16)	V 118 COM LAB	74				
		V119 COM LAB	75				
		V120 COM LAB	76				
		V 05 /5A PHYSICS LAB	77				
		V 06 CHEMISTRY LAB	165				
		V 07 PCB LAB	166				
		V REAR ENTRY 1 ST FLR	167				
		V STAIRCASE 1 ST FLR	168				
		V VISITORS AREA 1 ST FLR	5				
		V REAR CORIDOR 1 ST FLR	169				
		V OPEN CUBICALS REAR	6				

		V OUTSIDE SEMINAR HALL	170				
		V REAR CORIDOR 1 ST FLR	171				
		V 105 SEMINAR HALL	172				
		V REAR STAIRES	173				
		V REAR ENTRY GRD FLR	174				
VIT L 3	DVR9 (08)	LAB 1	78				
		LIBRARY VP	79				
		LAB 3	80				
		LAB 4	81				
		LAB 5	82				
		LAB 6	83				
		LAB 7	84				
		LAB 17	85				
VIT LAB	DVR 10 (8)	LAB 9	86				
		LAB 10	87			X	No camera
		LAB 11	88				
		LAB 12	89				
		LAB 13	90				
		LAB 14	91			X	Camera faulty
		LAB 15	92			X	Camera faulty
		LAB 16	93				
M 1	DVR11 (05)	RECEPTION	94				
		OUTSIDE LIFT 3 & 4	95				
		STAIRCASE FRONT	96				
		OUTSIDE LIFT 1 & 2	97				
		STAIRCASE REAR	98				
M 2	DVR12 (04)	STAIRCASE REAR	99				DVR Power supply faulty.
		OUTSIDE LIFT 1 & 2	100				
		STAIRCASE FRONT	101				
		LAB 201	102				
M 3	DVR13 (08)	LOBBY	103				
		LAB 312	104				
		LAB 310	105				
		STAIRCASE FRONT	106				
		OUTSIDE LIFT 1 & 2	107				
		LAB 313	108				
		STAIRCASE REAR	109				
		LAB 314	110				
M 4	DVR14 (08)	LOBBY	111				
		LAB 414	112				
		LAB 411	113				
		STAIRCASE FRONT	114				
		LAB 401	115				
		TOWARDS VIT TERRACE	116				
		STAIRCASE REAR	117				
		OUTSIDE LIFT 1 & 2	118				
M 5	DVR15 (10)	STAIRCASE FRONT	119				
		STAIRCASE REAR	120				
		LAB 516	121				
		LAB 512	122				
		LAB 510	123				
		LAB 509	124				
		LAB 514	125				
		LAB 518	126				
		OUTSIDE LIFT 1 & 2	127				

M 6	DVR16 (04)	LAB 515	128	✓		
		STAIRCASE FRONT	129	✓		
		LOBBY	130	✓		
		STAIRCASE REAR	131	✓		
M 7	DVR 17 (09)	OFFICE MMS	132	✓		
		OFFICE CORRIDOR	133	✓		
		STAIRCASE REAR	134	✓		
		STAIRCASE FRONT	135	✓		
		RECEPTION LOBBY	136	✓		
		PANTRY	137	✓		
		LIFT 1	138		X	camera faulty
		LIFT 2	139		X	camera faulty
RG	DVR 18 (03)	LIFT 3	140	✓		
		LIFT 4	141	✓		
		REAR GATE ENTRY	145	✓		
S	DVR 19 (16)	STP AREA	146			OFFLINE
		ROAD FROM RG	147	✓		
		OUT SIDE ENTRY POINT	148	✓		
		RECEPTION	149	✓		
		KARAOKE ROOM	150	✓		
		TT ROOM	151	✓		
		MERCHANTILE ROOM	152	✓		
		CHESS ROOM	153	✓		
Y	DVR 20 (10)	GAME ZONE	154	✓		
		MEETING ROOM	155	✓		
		BAG RACK	194	✓		
		OPP.CCD FLOOR	156	✓		
		OPP.CCD FLOOR	157	✓		
		OUTSIDE SICK ROOM	158	✓		
		GLASS DOOR ENTRY	159	✓		
		READING ROOM	160	✓		
		READING ROOM	161	✓		
		LAB	162	✓		
M GATE	DVR 21	LAB CORIDOR	163	✓		
		1 ST FLR ENTRY TO X BLOK	164	✓		
		Y BLK STAFF ROOM	177	✓		
		4 C AREA	195	✓		
M GATE	DVR 21	MAIN GATE CAMPUS	1	✓		
		2 ND GATE	192	✓		
		PARKING	193	✓		

TOTAL 195CAMS

DVR SERVICEABILITY STATUS

DVR	LOCATION	SERVICEABLE	NETCO NNECT	RECORD ING	HDD	REMARK
VP	V - PLACEMENT			62	1 TB	
VIT	RECEPTION			36	1 TB	
VSIT	OFFICE			.	2 TB	
VIT D BLOCK	D-103			32	2 TB	
VIT E BLOCK	E-102			27	2 TB	

X1	OFFICE		36	2 TB
X	OFFICE		22	1 TB
VP LAB	V-123		58	4 TB
B 1	L-014		35	1 TB
B 2	L-003		38	1 TB
M- 1	REAR DUCT		68	2 TB
M- 2	REAR DUCT		22	1 TB
M- 3	REAR DUCT		52	2 TB
M- 4	REAR DUCT		42	2 TB
M- 5	REAR DUCT			2 TB
M- 6	REAR DUCT		31	1 TB
M-7	LOBBY ROOF		28	2 TB
RG	RG		23	1 TB
Y	OUT SIDE READING ROOM		18	1 TB
S	GR.FLR. RECPT.		33	2 TB
G	NR.STAIRE CASE		28	2 TB
M GATE	SEC OFF		45	1 TB

CCTV REPORT IN NUTSHELL

TIME TAKEN FOR MAINTENANCE

SPECIFIC WORK DONE

WORK REQUIRED TO BE DONE

NO OF WORKERS REPORTED FOR MAINTENANCE

CLIENT REMARKS

M.B. Rajan
Majur *Rajan*
(RS)

() ()
ARNAV ENTERPRISES

SEC SUP

(Signature)
SEC OFFICER

MONTHLY CCTV SERVICEABILITY REPORT:

SUBMITTED ON

BY ARNAV ENTERPRISES

BLOCK NO	DVR NO	LOCATION	CAM NO	CLEANED	STATUS		REMARK / FAULT
					WORKING	NOT WORKING	
VP	DVR 3 (04)	RECEPTION	2				
		PASSAGE BET W & VP	3				
		OFFICE GRD FLR	4				
		2 ND FLOOR CORRIDOR	7				
VIT	DVR 1 (12)	BASEMENT CORRIDOR 1	8				
		BASEMENT LIFT	9				
		BASEMENT CORRIDOR 2	10				
		VIT RECEPTION	13				
		VIT ENTRY 1	14				DOWN FACULTY
		VIT PLAZA1 WALL	15				
		VIT COMPUTER CENTRE	16				
		VIT PLAZA 2	17				DOWN FACULTY
		DIRECTOR'S OFFICE	20				
		PAPER PRINTING	143				
		VP LAB 2	175				
		VIT ACCOUNT A BLK	176				
		VSIT	DVR2 (12)	'X' BLOCK ENTRY	23		
'X' OFFICE -2	24						
'X' GRD FLR CORRIDOR 1	25						DOWN FACULTY
'X' GRD FLR CORRIDOR 2	26						DOWN FACULTY
'X' OFFICE	27						
GROUND 1	31						
PARKING STUDENTS	32						
LIBRARY VSIT	144						
TREE AREA X BLK	178						
X 19 REASERCH CENTRE	179						
X 016 VSIT OFFICE	180						
X11 VSIT STAFF ROOM	181						
D	DVR4 (15)			BASEMENT CORRIDOR 3	11		
		BASEMENT GYM	12				
		VIT CANTEEN	18				
		VIT ENTRY 2	19				
		D-101 FACULTY	33				
		D-102 CLASS	34				
		D-103 OFFICE/DVR	35				
		D-105 CLASS	36				
		D-201 CLASS	37				
		D-202 CLASS	38				
		D-204 CLASS	39				
		D-301 CLASS	40				
		D-302 CLASS	41				
D-304 CLASS	42						
CANTEEN C BLK	190						
E	DVR 5	GROUND 2	21				

	(14)	REAR GATE	22				
		E-101 CLASS	43				
		E-102 OFFICE/DVR	44				
		E-104 STATIONARY	45				
		M BLK CANTEEN	191				
		E-105 FACULTY	46				
		E-105 FACULTY	47				
		E-201 CLASS	48				
		E-204 CLASS	49				
		E-301 CLASS	50				
		E-303 CLASS	51				
		WORKSHOP M BLOCK	52				
		CANTEEN M BLOCK	142				
G	DVR 21 (8)	VIT CC02	182				
		VIT CC 03	183				
		G 201 REFERENCE	184				
		G BLK 1 ST FLR ENTRY	185				
		READING HALL	186				
		LIBRARY VIT 201	187				
		G 301 LIB	188				
		STORE F	189				
X1	DVR7 (16)	X-101 CLASS	53				
		X-102 CLASS	54				
		X-103 A LAB	55				
		X-103 B LAB	56				
		X-107 CLASS	57				
		X-108 CLASS	58				
		X-109 FACULTY ROOM	59				
		X-110 CLASS	60			X	can't find
		X-111 CLASS	61				
		X-112 CLASS	62				
		X-113 CLASS	63				
		X-114 LAB	64				
		X-115 LAB	65				
		X-116 LAB	66				
		X-117 CLASS	67				
		X-118 CLASS	68				
X	DVR6 (08)	X-015 EXAM CELL	28				
		'X' 1 ST FLR CORRIDOR	29				
		'X' 1 ST FLR DEAD END	30				
		X-119 LAB	69				
		X-120 LAB	70				
		X-121 LAB	71				
		X-122 LAB	72				
		X-123 LAB	73				
VP LAB	DVR8 (16)	V 118 COM LAB	74				
		V119 COM LAB	75				
		V120 COM LAB	76				
		V 05 /5A PHYSICS LAB	77				
		V 06 CHEMISTRY LAB	165				
		V 07 PCB LAB	166				
		V REAR ENTRY 1 ST FLR	167				
		V STAIRCASE 1 ST FLR	168				
		V VISITORS AREA 1 ST FLR	5				
		V REAR CORIDOR 1 ST FLR	169				
		V OPEN CUBICALS REAR	6				

		V OUTSIDE SEMINAR HALL	170				
		V REAR CORIDOR 1 ST FLR	171			X	CAMERA
		V 105 SEMINAR HALL	172				
		V REAR STAIRES	173				
		V REAR ENTRY GRD FLR	174				
VIT L 3	DVR9 (08)	LAB 1	78				
		LIBRARY VP	79				
		LAB 3	80				
		LAB 4	81				
		LAB 5	82				
		LAB 6	83				
		LAB 7	84				
		LAB 17	85				
VIT LAB	DVR 10 (8)	LAB 9	86				
		LAB 10	87				CAMERA
		LAB 11	88				
		LAB 12	89				
		LAB 13	90				
		LAB 14	91				CAMERA
		LAB 15	92				Removed
		LAB 16	93				
M 1	DVR11 (05)	RECEPTION	94				
		OUTSIDE LIFT 3 & 4	95				
		STAIRCASE FRONT	96				
		OUTSIDE LIFT 1 & 2	97				
		STAIRCASE REAR	98				
M 2	DVR12 (04)	STAIRCASE REAR	99				
		OUTSIDE LIFT 1 & 2	100				
		STAIRCASE FRONT	101				
		LAB 201	102				
M 3	DVR13 (08)	LOBBY	103				
		LAB 312	104				
		LAB 310	105				
		STAIRCASE FRONT	106				
		OUTSIDE LIFT 1 & 2	107				
		LAB 313	108				
		STAIRCASE REAR	109				
		LAB 314	110				
M 4	DVR14 (08)	LOBBY	111				
		LAB 414	112				
		LAB 411	113				
		STAIRCASE FRONT	114				
		LAB 401	115				
		TOWARDS VIT TERRACE	116				
		STAIRCASE REAR	117				
		OUTSIDE LIFT 1 & 2	118				
M 5	DVR15 (10)	STAIRCASE FRONT	119				
		STAIRCASE REAR	120				
		LAB 516	121				
		LAB 512	122				
		LAB 510	123				
		LAB 509	124				
		LAB 514	125				
		LAB 518	126				
		OUTSIDE LIFT 1 & 2	127				

M 6	DVR16 (04)	LAB 515	128			
		STAIRCASE FRONT	129			
		LOBBY	130			
		STAIRCASE REAR	131			
		OFFICE MMS	132			
M 7	DVR17 (09)	OFFICE CORRIDOR	133			
		STAIRCASE REAR	134			
		STAIRCASE FRONT	135			
		RECEPTION LOBBY	136			
		PANTRY	137			
		LIFT 1	138			
		LIFT 2	139			
		LIFT 3	140			
RG	DVR 18 (03)	REAR GATE ENTRY	145			
		STP AREA	146			
		ROAD FROM RG	147			
S	DVR 19 (16)	OUT SIDE ENTRY POINT	148			
		RECEPTION	149			
		KARAOKE ROOM	150			
		TT ROOM	151			
		MERCHANTILE ROOM	152			
		CHESS ROOM	153			
		GAME ZONE	154			
		MEETING ROOM	155			
		BAG RACK	194			
Y	DVR 20 (10)	OPP.CCD FLOOR	156			
		OPP.CCD FLOOR	157			
		OUTSIDE SICK ROOM	158			
		GLASS DOOR ENTRY	159			
		READING ROOM	160			
		READING ROOM	161			
		LAB	162			
		LAB CORIDOR	163			
		1 ST FLR ENTRY TO X BLOK	164			
		Y BLK STAFF ROOM	177			
M GATE	DVR 21	4 C AREA	195			
		MAIN GATE CAMPUS	1			
		2 ND GATE	192			
		PARKING	193			

TOTAL 195CAMS						
DVR SERVICEABILITY STATUS						
DVR	LOCATION	SERVICEABLE	NETCO NNECT	RECORD ING	HDD	REMARK
VP	V- PLACEMENT				1 TB	
VIT	RECEPTION				1 TB	
VSIT	OFFICE				2 TB	
VIT D BLOCK	D-103				2 TB	
VIT E BLOCK	E-102				2 TB	

X1	OFFICE			2 TB	
X	OFFICE			1 TB	
VP LAB	V-123			4 TB	
B 1	L-014			1 TB	
B 2	L-003			1 TB	
M- 1	REAR DUCT			2 TB	
M- 2	REAR DUCT			1 TB	
M- 3	REAR DUCT			2 TB	
M- 4	REAR DUCT			2 TB	
M- 5	REAR DUCT			2 TB	
M- 6	REAR DUCT			1 TB	
M-7	LOBBY ROOF			2 TB	
RG	RG			1 TB	
Y	OUT SIDE READINGRO OM			1 TB	
S	GR.FLR. RECPT.			2 TB	
G	NR.STAIRE CASE			2 TB	
M GATE	SEC OFF			1 TB	

CCTV REPORT IN NUTSHELL	
TIME TAKEN FOR MAINTENANCE	2 hours
SPECIFIC WORK DONE	24 work done
WORK REQUIRED TO BE DONE	
NO OF WORKERS REPORTED FOR MAINTENANCE	2
CLIENT REMARKS	
<p><i>(Signature)</i> <i>(Signature)</i></p> <p>() () <i>(Signature)</i></p> <p>ARNAV ENTERPRISES SEC SUP SEC OFFICER</p>	

13/13, 4/12/21

MONTHLY CCTV SERVICEABILITY REPORT: for the month of Dec 21
SUBMITTED ON 14/12/21
BY ARNAV ENTERPRISES

BLOCK NO	DVR NO	LOCATION	CAM NO	CLEANED	STATUS		REMARK / FAULT		
					WORKING	NOT WORKING			
VP	DVR 3 (04)	RECEPTION	2		✓				
		PASSAGE BET W & VP	3		✓				
		OFFICE GRD FLR	4		✓				
		2 ND FLOOR CORRIDOR	7		✓				
VIT	DVR 1 (12)	BASEMENT CORRIDOR 1	8		✓				
		BASEMENT LIFT	9		✓				
		BASEMENT CORRIDOR 2	10		✓				
		VIT RECEPTION	13		✓				
		VIT ENTRY 1	14		✓				
		VIT PLAZA1 WALL	15		✓	X	Cable Faulty need to replace		
		VIT COMPUTER CENTRE	16		✓				
		VIT PLAZA 2	17		✓				
		DIRECTOR'S OFFICE	20		✓				
		PAPER PRINTING	143		✓				
		VP LAB 2	175		✓				
		VIT ACCOUNT A BLK	176		✓				
		VSIT	DVR2 (12)	'X' BLOCK ENTRY	23		✓		
				'X' OFFICE -2	24		✓		
'X' GRD FLR CORRIDOR 1	25					X	camera of faculty		
'X' GRD FLR CORRIDOR 2	26				✓				
'X' OFFICE	27				✓				
GROUND 1	31				✓				
PARKING STUDENTS	32				✓				
LIBRARY VSIT	144				✓				
TREE AREA X BLK	178				✓				
X 19 REASERCH CENTRE	179				✓				
X 016 VSIT OFFICE	180				✓				
D	DVR4 (15)	X11 VSIT STAFF ROOM	181		✓				
		BASEMENT CORRIDOR 3	11		✓				
		BASEMENT GYM	12		✓				
		VIT CANTEEN	18		✓				
		VIT ENTRY 2	19		✓				
		D-101 FACULTY	33		✓				
		D-102 CLASS	34		✓				
		D-103 OFFICE/DVR	35		✓				
		D-105 CLASS	36		✓				
		D-201 CLASS	37		✓				
		D-202 CLASS	38		✓				
		D-204 CLASS	39		✓				
		D-301 CLASS	40		✓				
		D-302 CLASS	41		✓				
D-304 CLASS	42		✓						
E	DVR 5	CANTEEN C BLK	190		✓				
		GROUND 2	21		✓				

	(14)	REAR GATE	22				
		E-101 CLASS	43		✓		
		E-102 OFFICE/DVR	44		✓		
		E-104 STATIONARY	45		✓		
		M BLK CANTEEN	191		✓		
		E-105 FACULTY	46		✓		
		E-105 FACULTY	47		✓		
		E-201 CLASS	48		✓		
		E-204 CLASS	49		✓		
		E-301 CLASS	50		✓		
		E-303 CLASS	51		✓		
		WORKSHOP M BLOCK	52		✓		
		CANTEEN M BLOCK	142		✓		
G	DVR 21 (8)	VIT CC02	182		✓		
		VIT CC 03	183		✓		
		G 201 REFERENCE	184		✓		
		G BLK 1 ST FLR ENTRY	185		✓		
		READING HALL	186		✓		
		LIBRARY VIT 201	187		✓		
		G 301 LIB	188		✓		
		STORE F	189		✓		
X1	DVR7 (16)	X-101 CLASS	53		✓		
		X-102 CLASS	54		✓		
		X-103 A LAB	55		✓		
		X-103 B LAB	56		✓		
		X-107 CLASS	57		✓		
		X-108 CLASS	58		✓		
		X-109 FACULTY ROOM	59		✓		
		X-110 CLASS	60		✓		
		X-111 CLASS	61		✓		
		X-112 CLASS	62		✓		
		X-113 CLASS	63		✓		
		X-114 LAB	64		✓		
		X-115 LAB	65		✓		
		X-116 LAB	66		✓		
		X-117 CLASS	67		✓		
		X-118 CLASS	68		✓		
X	DVR6 (08)	X-015 EXAM CELL	28		✓		
		'X' 1 ST FLR CORRIDOR	29		✓		
		'X' 1 ST FLR DEAD END	30		✓		
		X-119 LAB	69		✓		
		X-120 LAB	70		✓		
		X-121 LAB	71		✓		
		X-122 LAB	72		✓		
		X-123 LAB	73		✓		
VP LAB	DVR8 (16)	V 118 COM LAB	74		✓		4 channel power supply required
		V119 COM LAB	75		✓		
		V120 COM LAB	76		✓		
		V 05 /5A PHYSICS LAB	77		✓		
		V 06 CHEMISTRY LAB	165		✓		
		V 07 PCB LAB	166		✓		
		V REAR ENTRY 1 ST FLR	167		✓		
		V STAIRCASE 1 ST FLR	168		✓		
		V VISITORS AREA 1 ST FLR	5		✓		
		V REAR CORRIDOR 1 ST FLR	169		✓		
		V OPEN CUBICALS REAR	6		✓		

		V OUTSIDE SEMINAR HALL	170				
		V REAR CORIDOR 1 ST FLR	171				
		V 105 SEMINAR HALL	172				
		V REAR STAIRES	173				
		V REAR ENTRY GRD FLR	174				
VIT L 3	DVR9 (08)	LAB 1	78				
		LIBRARY VP	79				
		LAB 3	80				
		LAB 4	81				
		LAB 5	82				
		LAB 6	83				
		LAB 7	84				
		LAB 17	85				
VIT LAB	DVR 10 (8)	LAB 9	86				
		LAB 10	87		X	Camera Faulty	
		LAB 11	88		X		
		LAB 12	89				
		LAB 13	90				
		LAB 14	91			Camera Problem	
		LAB 15	92			Camera Problem	
		LAB 16	93				
M 1	DVR11 (05)	RECEPTION	94				
		OUTSIDE LIFT 3 & 4	95				
		STAIRCASE FRONT	96				
		OUTSIDE LIFT 1 & 2	97				
		STAIRCASE REAR	98				
M 2	DVR12 (04)	STAIRCASE REAR	99				
		OUTSIDE LIFT 1 & 2	100				
		STAIRCASE FRONT	101				
		LAB 201	102				
M 3	DVR13 (08)	LOBBY	103				
		LAB 312	104				
		LAB 310	105				
		STAIRCASE FRONT	106				
		OUTSIDE LIFT 1 & 2	107				
		LAB 313	108				
		STAIRCASE REAR	109				
		LAB 314	110				
M 4	DVR14 (08)	LOBBY	111				
		LAB 414	112				
		LAB 411	113				
		STAIRCASE FRONT	114				
		LAB 401	115				
		TOWARDS VIT TERRACE	116				
		STAIRCASE REAR	117				
		OUTSIDE LIFT 1 & 2	118				
M 5	DVR15 (10)	STAIRCASE FRONT	119				
		STAIRCASE REAR	120				
		LAB 516	121				
		LAB 512	122				
		LAB 510	123				
		LAB 509	124				
		LAB 514	125				
		LAB 518	126				
		OUTSIDE LIFT 1 & 2	127				


M 6	DVR16 (04)	LAB 515	128		✓		
		STAIRCASE FRONT	129		✓		
		LOBBY	130		✓		
		STAIRCASE REAR	131		✓		
		OFFICE MMS	132		✓		
M 7	DVR17 (09)	OFFICE CORRIDOR	133		✓		
		STAIRCASE REAR	134		✓		
		STAIRCASE FRONT	135		✓		
		RECEPTION LOBBY	136		✓		
		PANTRY	137		✓		
		LIFT 1	138		✓		
		LIFT 2	139		✓		
		LIFT 3	140		✓		
RG	DVR 18 (03)	REAR GATE ENTRY	145		✓		
		STP AREA	146		✓		offline
		ROAD FROM RG	147		✓		
S	DVR 19 (16)	OUT SIDE ENTRY POINT	148		✓		
		RECEPTION	149		✓		
		KARAOKE ROOM	150		✓		
		TT ROOM	151		✓		
		MERCHANTILE ROOM	152		✓		
		CHESS ROOM	153		✓		
		GAME ZONE	154		✓		
		MEETING ROOM	155		✓		
		BAG RACK	194		✓		
		Y	DVR 20 (10)	OPP.CCD FLOOR	156		✓
OPP.CCD FLOOR	157				✓		
OUTSIDE SICK ROOM	158				✓		
GLASS DOOR ENTRY	159				✓		
READING ROOM	160				✓		
READING ROOM	161				✓		
LAB	162				✓		
LAB CORIDOR	163				✓		
1 ST FLR ENTRY TO X BLOK	164				✓		
Y BLK STAFF ROOM	177				✓		
4 C AREA	195				✓		
M GATE	DVR 21	MAIN GATE CAMPUS	1		✓		
		2 ND GATE	192		✓		
		PARKING	193		✓		


TOTAL 195CAMS						
DVR SERVICEABILITY STATUS						
DVR	LOCATION	SERVICEABLE	NETCO NNECT	RECORD ING	HDD	REMARK
VP	V- PLACEMENT			64	1 TB	✓
VIT	RECEPTION			40	1 TB	✓
VSIT	OFFICE			68	2 TB	✓
VIT D BLOCK	D-103			60	2 TB	✓
VIT E BLOCK	E-102			95	2 TB	✓

X1	OFFICE		47	2 TB	✓
X	OFFICE		35	1 TB	✓
VP LAB	V-123		70	4 TB	✓
B 1	L-014		NO HDD	1 TB	✓
B 2	L-003		49	1 TB	✓
M- 1	REAR DUCT		Today	2 TB	✓
M- 2	REAR DUCT		45	1 TB	✓
M- 3	REAR DUCT		70	2 TB	✓
M- 4	REAR DUCT		75	2 TB	✓
M- 5	REAR DUCT		65	2 TB	✓
M- 6	REAR DUCT		34	1 TB	✓
M-7	LOBBY ROOF		39	2 TB	✓
RG	RG		25	1 TB	✓
Y	OUT SIDE READING ROOM		23	1 TB	✓
S	GR.FLR. RECPT.		90	2 TB	✓
G	NR.STAIRE CASE		34	2 TB	✓
M GATE	SEC OFF		20	1 TB	✓

CCTV REPORT IN NUTSHELL

TIME TAKEN FOR MAINTENANCE	3 Days
SPECIFIC WORK DONE	PM work CCTV system
WORK REQUIRED TO BE DONE	
NO OF WORKERS REPORTED FOR MAINTENANCE	3
CLIENT REMARKS	


 Amit Khandelwal
 (00) (00)
 ARNAV ENTERPRISES SEC SUP


 (C P M Janye)
 SEC OFFICER

MONTHLY CCTV SERVICEABILITY REPORT: AUG 21
SUBMITTED ON (21, 28/9/21)
BY ARNAV ENTERPRISES

BLOCK NO	DVR NO	LOCATION	CAM NO	CLEANED	STATUS		REMARK / FAULT
					WORKING	NOT WORKING	
VP	DVR 3 (04)	RECEPTION	2		✓		
		PASSAGE BET W & VP	3		✓		
		OFFICE GRD FLR	4		✓		
		2 ND FLOOR CORRIDOR	7		✓		
VIT	DVR 1 (12)	BASEMENT CORRIDOR 1	8		✓		
		BASEMENT LIFT	9		✓		
		BASEMENT CORRIDOR 2	10		✓		
		VIT RECEPTION	13			X	camera faulty
		VIT ENTRY 1	14		✓		
		VIT PLAZA1 WALL	15			X	wire problem
		VIT COMPUTER CENTRE	16		✓		
		VIT PLAZA 2	17		✓		
		DIRECTOR'S OFFICE	20		✓		
		PAPER PRINTING	143		✓		
		VP LAB 2	175		✓		
		VIT ACCOUNT A BLK	176		✓		
		VSIT	DVR2 (12)	'X' BLOCK ENTRY	23		✓
'X' OFFICE -2	24				✓		
'X' GRD FLR CORRIDOR 1	25				✓		
'X' GRD FLR CORRIDOR 2	26				✓		
'X' OFFICE	27				✓		
GROUND 1	31				✓		
PARKING STUDENTS	32				✓		
LIBRARY VSIT	144				✓		
TREE AREA X BLK	178				✓		
X 19 REASERCH CENTRE	179				✓		
X 016 VSIT OFFICE	180				✓		
X11 VSIT STAFF ROOM	181				✓		
D	DVR4 (15)			BASEMENT CORRIDOR 3	11		✓
		BASEMENT GYM	12		✓		
		VIT CANTEEN	18		✓		
		VIT ENTRY 2	19			X	Power Adapter faulty
		D-101 FACULTY	33		✓		
		D-102 CLASS	34		✓		
		D-103 OFFICE/DVR	35		✓		
		D-105 CLASS	36		✓		
		D-201 CLASS	37		✓		
		D-202 CLASS	38		✓		
D-204 CLASS	39		✓				

		D-301 CLASS	40		✓		
		D-302 CLASS	41		✓		
		D-304 CLASS	42		✓		
		CANTEEN C BLK	190		✓		
E	DVR 5 (14)	GROUND 2	21		✓		
		REAR GATE	22		✓		
		E-101 CLASS	43		✓		
		E-102 OFFICE/DVR	44		✓		
		E-104 STATIONARY	45		✓		
		M BLK CANTEEN	191		✓		
		E-105 FACULTY	46		✓		
		E-105 FACULTY	47		✓		
		E-201 CLASS	48		✓		
		E-204 CLASS	49		✓		
		E-301 CLASS	50		✓		
		E-303 CLASS	51		✓		
		WORKSHOP M BLOCK	52		✓		
		CANTEEN M BLOCK	142		✓		
G	DVR 21 (8)	VIT CC02	182		✓		
		VIT CC 03	183		✓		
		G 201 REFERENCE	184		✓		
		G BLK 1 ST FLR ENTRY	185		✓		
		READING HALL	186		✓		
		LIBRARY VIT 201	187		✓		
		G 301 LIB	188		✓		
		STORE F	189		✓		
X1	DVR7 (16)	X-101 CLASS	53		✓		
		X-102 CLASS	54		✓		
		X-103 A LAB	55		✓		
		X-103 B LAB	56		✓		
		X-107 CLASS	57		✓		
		X-108 CLASS	58		✓		
		X-109 FACULTY ROOM	59		✓		
		X-110 CLASS	60		✓		
		X-111 CLASS	61		✓		
		X-112 CLASS	62		✓	X	Cam jewelry
		X-113 CLASS	63		✓		
		X-114 LAB	64		✓		
		X-115 LAB	65		✓		
		X-116 LAB	66		✓		
		X-117 CLASS	67		✓		
		X-118 CLASS	68		✓		
X	DVR6 (08)	X-015 EXAM CELL	28		✓		
		'X' 1 ST FLR CORRIDOR	29		✓		
		'X' 1 ST FLR DEAD END	30		✓	X	Power supply facility
		X-119 LAB	69		✓		
		X-120 LAB	70		✓		
		X-121 LAB	71		✓		
		X-122 LAB	72		✓		
		X-123 LAB	73		✓		
VP LAB	DVR8 (16)	V 118 COM LAB	74		✓		
		V119 COM LAB	75		✓		
		V120 COM LAB	76		✓		
		V 05 /5A PHYSICS LAB	77		✓		
		V 06 CHEMISTRY LAB	165		✓		

		V 07 PCB LAB	166			✓		
		V REAR ENTRY 1 ST FLR	167			✓		
		V STAIRCASE 1 ST FLR	168			✓		
		V VISITORS AREA 1 ST FLR	5			✓		
		V REAR CORIDOR 1 ST FLR	169			✓		
		V OPEN CUBICALS REAR	6			✓		
		V OUTSIDE SEMINAR HALL	170			✓		
		V REAR CORIDOR 1 ST FLR	171			✓		
		V 105 SEMINAR HALL	172			✓		
		V REAR STAIRES	173			✓		
		V REAR ENTRY GRD FLR	174			✓		
VIT L 3	DVR9 (08)	LAB 1	78			✓		
		LIBRARY VP	79			✓		
		LAB 3	80			✓		
		LAB 4	81			✓		
		LAB 5	82			✓		
		LAB 6	83			✓		
		LAB 7	84			✓		
		LAB 17	85			✓		
VIT LAB L 14	DVR 10 (8)	LAB 9	86			✓		
		LAB 10	87			✓		
		LAB 11	88			✓		
		LAB 12	89			✓		
		LAB 13	90			✓		
		LAB 14	91			✓		
		LAB 15	92			✓		
		LAB 16	93			✓		
M 1	DVR11 (05)	RECEPTION	94			✓		
		OUTSIDE LIFT 3 & 4	95			✓		
		STAIRCASE FRONT	96			✓		
		OUTSIDE LIFT 1 & 2	97			✓		
		STAIRCASE REAR	98			✓		
M 2	DVR12 (04)	STAIRCASE REAR	99			✓		
		OUTSIDE LIFT 1 & 2	100			✓		
		STAIRCASE FRONT	101			✓		
		LAB 201	102			✓		
M 3	DVR13 (08)	LOBBY	103			✓		
		LAB 312	104			✓		
		LAB 310	105			✓		
		STAIRCASE FRONT	106			✓		
		OUTSIDE LIFT 1 & 2	107			✓		
		LAB 313	108			✓		
		STAIRCASE REAR	109			✓		
		LAB 314	110			✓		
M 4	DVR14 (08)	LOBBY	111			✓		
		LAB 414	112			✓		
		LAB 411	113			✓		
		STAIRCASE FRONT	114			✓		
		LAB 401	115			✓		
		TOWARDS VIT	116			✓		

		TERRACE					
		STAIRCASE REAR	117			✓	
		OUTSIDE LIFT 1 & 2	118			✓	
M 5	DVR15 (10)	STAIRCASE FRONT	119			✓	
		STAIRCASE REAR	120			✓	
		LAB 516	121			✓	
		LAB 512	122			✓	
		LAB 510	123			✓	
		LAB 509	124			✓	
		LAB 514	125			✓	
		LAB 518	126			✓	
		OUTSIDE LIFT 1 & 2	127			✓	
		LAB 515	128			✓	
M 6	DVR16 (04)	STAIRCASE FRONT	129			✓	
		LOBBY	130			✓	
		STAIRCASE REAR	131			✓	
		OFFICE MMS	132			✓	
M 7	DVR17 (09)	OFFICE CORRIDOR	133			✓	
		STAIRCASE REAR	134			✓	
		STAIRCASE FRONT	135			✓	
		RECEPTION LOBBY	136			✓	
		PANTRY	137			✓	
		LIFT 1	138			✓	
		LIFT 2	139			✓	
		LIFT 3	140			✓	
		LIFT 4	141			✓	
RG	DVR 18 (03)	REAR GATE ENTRY	145			✓	
		STP AREA	146			✓	
		ROAD FROM RG	147			✓	
S	DVR 19 (16)	OUT SIDE ENTRY POINT	148			✓	<i>Cameras Serviceable Seen on Local PC but not seen in M/G. Internet Problem in S block DVR (Our system problem)</i>
		RECEPTION	149			✓	
		KARAOKE ROOM	150			✓	
		TT ROOM	151			✓	
		MERCHANTILE ROOM	152			✓	
		CHESS ROOM	153			✓	
		GAME ZONE	154			✓	
		MEETING ROOM	155			✓	
		BAG RACK	194			✓	
Y	DVR 20 (10)	OPP.CCD FLOOR	156			✓	
		OPP.CCD FLOOR	157			✓	
		OUTSIDE SICK ROOM	158			✓	
		GLASS DOOR ENTRY	159			✓	
		READING ROOM	160			✓	
		READING ROOM	161			✓	
		LAB	162			✓	
		LAB CORIDOR	163			✓	
		1 ST FLR ENTRY TO X BLOK	164			✓	
		Y BLK STAFF ROOM	177			✓	
		4 C AREA	195			✓	
M GATE	DVR 21	MAIN GATE CAMPUS	1			✓	
		2 ND GATE	192			✓	
		PARKING	193			✓	

TOTAL 195CAMs

DVR SERVICEABILITY STATUS

DVR	LOCATION	SERVICEABLE	NETCO NNECT	RECORD ING	HDD	REMARK
VP	V- PLACEMENT			71 Days	1 TB	
VIT	RECEPTION			18 Days	1 TB	
VSIT	OFFICE			54 Days	2 TB	
VIT D BLOCK	D-103			68 Days	2 TB	
VIT E BLOCK	E-102			96 Days	2 TB	
X1	OFFICE			18 Days	2 TB	
X	OFFICE			33 Days	1 TB	
VP LAB	V-123			24 Days	4 TB	
B 1	L-014			62 Days	1 TB	
B 2	L-003				1 TB	
M-1	REAR DUCT			3 Days	2 TB	
M-2	REAR DUCT			75 Days	1 TB	
M-3	REAR DUCT			72 Days	2 TB	
M-4	REAR DUCT			74 Days	2 TB	
M-5	REAR DUCT			41 Days	2 TB	
M-6	REAR DUCT			32 Days	1 TB	
M-7	LOBBY ROOF			30 Days	2 TB	
RG	RG			22 Days	1 TB	
Y	OUT SIDE READING ROOM			31 Days	1 TB	
S	GR.FLR. RECPT.			04 Days	2 TB	
G	NR.STAIRE CASE			15 Days	2 TB	
M GATE	SEC OFF			16 Days	1 TB	

CCTV REPORT IN NUTSHELL

TIME TAKEN FOR MAINTENANCE	
SPECIFIC WORK DONE	
WORK REQUIRED TO BE DONE	
NO OF WORKERS REPORTED FOR MAINTENANCE	
CLIENT REMARKS	

Amir P. Jante
Majeda B. Jante

() ()
 ARNAV ENTERPRISES

() ()
 SEC SUF

() ()
 SEC OFFICER

Jante
 (P.M. Jante)